

# Oil Field Environmental Incident Summary

**Incident:** 20150706144010

**Date/Time of Notice:** 07/06/2015 14:40

**Responsible Party:** Petro-Hunt, LLC

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** Killdeer Mountain Pipeline

**Field Name:** LITTLE KNIFE

**Well File #:**

**Date Incident:** 7/2/2015

**Time Incident:** 15:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 147

**Rng:** 97

**Sec:** 22

**Qtr:** SE

**Location Description:**

**Submitted By:** Rodney Krogh

**Received By:**

**Contact Person:** Rodney Krogh  
813 123rd Ave SW  
Killdeer, ND 58640

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	800	Gallons				

**Description of Other Released Contaminant:**

Unprocessed natural gas in mcf

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

explosive atmosphere at leak until pipeline is depressured

**Areal Extent:**

**Potential Environmental Impacts:**

Not likely to have environmental impact

**Action Taken or Planned:**

Pipeline is shut in and de-pressured. Line will be repaired. Line will be bored under the hill when boring crew is available.

**Wastes Disposal Location:** NA

**Agencies Involved:**

**Updates**

---

**Date:** 7/6/2015      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill possibly may have impacted the surrounding area. Follow-up is necessary.

---

**Date:** 7/22/2015      **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I arrived at the site at 14:46. The weather was sunny, 90°F, with the wind from the southeast 10-15 mph. Talked to the company representative, he indicated this was the second time the soil has slumped causing the pipeline to break. The company will be boring the pipeline in this area, to prevent future slumping. There has been a lot of dirt work done around the area of pipeline. The pipeline has been left exposed. The south end of the pit has been built-up. Did not see any stained area in excavation. They have fenced off the pit area. More follow-up needed. The site is 2.2 miles from the gravel road. 46.89505, -102.86605